

 Early Warning System

ADB-49319-001

Cyclone Pam Road Reconstruction Project



Quick Facts

Countries	Vanuatu
Financial Institutions	Asian Development Bank (ADB)
Status	Approved
Bank Risk Rating	B
Voting Date	2015-11-25
Borrower	Government of Republic of Vanuatu, Ministry of Finance & Economic Management
Sectors	Transport
Investment Type(s)	Grant, Loan
Investment Amount (USD)	\$ 16.30 million
Loan Amount (USD)	\$ 3.80 million
Grant Amount (USD)	\$ 12.49 million



Project Description

According to ADB website, the Cyclone Pam Road Reconstruction Project will support the efforts of the Government of the Republic of Vanuatu to reconstruct, and climate and disaster proof, the transport sector infrastructure on Efate ring road damaged by the Cyclone Pam floods and storm surges during 12-14 March 2015. The impact will be accelerated economic and social recovery in Vanuatu's Cyclone Pam affected provinces.



Investment Description

- Asian Development Bank (ADB)



Contact Information

Project Officer: Indrawansa, P.P.G.P.P.

Pacific Department

No contact information provided at the time of disclosure.

ACCOUNTABILITY MECHANISM OF ADB

The Accountability Mechanism is an independent complaint mechanism and fact-finding body for people who believe they are likely to be, or have been, adversely affected by an Asian Development Bank-financed project. If you submit a complaint to the Accountability Mechanism, they may investigate to assess whether the Asian Development Bank is following its own policies and procedures for preventing harm to people or the environment. You can learn more about the Accountability Mechanism and how to file a complaint at: <http://www.adb.org/site/accountability-mechanism/main>



Bank Documents

- [Amendment to the Financing Agreement for Loans 3331 to 3332 and Grants 0459 to 0460-VAN: Cyclone Pam](#) [Original Source]
- [Contribution to the ADB Results Framework](#) [Original Source]
- [Country Economic Indicators](#) [Original Source]
- [Cyclone Pam Road Reconstruction Project - Additional Financing: Initial Environmental Examination](#) [Original Source]
- [Cyclone Pam Road Reconstruction Project - Eastern and Western Subprojects: Initial Environmental Exa](#) [Original Source]
- [Cyclone Pam Road Reconstruction Project: Community Consultation Plan](#) [Original Source]
- [Cyclone Pam Road Reconstruction Project: Procurement Plan](#) [Original Source]
- [Cyclone Pam Road Reconstruction Project: Project Administration Manual](#) [Original Source]
- [Cyclone Pam Road Reconstruction Project: Report and Recommendation of the President](#) [Original Source]
- [Cyclone Pam Road Reconstruction Project: Social Safeguards Due Diligence Report](#) [Original Source]
- [Emergency Assistance Coordination](#) [Original Source]
- [Environmental Assessment and Review Framework](#) [Original Source]
- [Financing Agreement \(Special Operations\) for Grants 0459-0460 and Loans 3331-3332-VAN: Cyclone Pam R](#) [Original Source]
- [Grant Agreement \(Global Environmental Facility\) for Grant 0461-VAN: Cyclone Pam Road Reconstruction](#) [Original Source]
- [Grant Agreement \(Special Operations\) for Grant 0540-VAN](#)
- [Loan Agreement \(Ordinary Operations \[Concessional\]\) for Loan 3552-VAN](#)
- [Procurement Classification](#) [Original Source]
- [Project Administration Manual](#)
- [Project Disclosure PDF](#) [Original Source]
- [Resettlement Framework](#) [Original Source]
- [Risk Assessment and Risk Management Plan](#) [Original Source]
- [Summary Assessment of Damage and Needs: Transport Sector](#) [Original Source]
- [Summary Poverty Reduction and Social Strategy](#) [Original Source]
- [Vanuatu: Post-Disaster Needs Assessment Executive Summary](#) [Original Source]



Other Related Projects

- ADB-49319-002 Cyclone Pam Road Reconstruction Project (additional financing)