Early Warning System

WB-P163856

Tuvalu Aviation Investment Project Additional Finance III

Early Warning System

Tuvalu Aviation Investment Project Additional Finance III

WB-P163856

Quick Facts

Countries	Tuvalu
Specific Location	Fongafale
Financial Institutions	World Bank (WB)
Status	Active
Bank Risk Rating	U
Voting Date	2017-11-16
Borrower	Government of Tuvalu
Sectors	Communications, Transport
Investment Type(s)	Grant
Investment Amount (USD)	$ 8.75 million
Project Cost (USD)	$ 8.75 million

Project Description

According to the bank documents, the proposed additional financing is necessary to finance: (i) design and construction of emergency repairs addressing pavement defects on Funafuti runway. These failures have resulted from water pressure under the recently paved runway and will see sub-runway venting drains installed and possibly pumps; (ii) the supervision cost for the runway civil works and construction of the flight services center and fire tender shelter—including through the defect liability period; (iii) ongoing monitoring of the impact of the civil works on the sub-runway water pressures; (iv) a budget shortfall under the parent project due to foreign exchange fluctuations and higher than anticipated supervision costs; and, (v) enhanced GBV and VAC prevention activities, OHS and ESMP monitoring tools and trainings for civil works contractors.

Investment Description

- World Bank (WB)

Contact Information

Implementing Agencies
Name:Ministry of Transport and Communications Contact:Vitoli Iosefa
Title:PST Manager
Email:faaoga@gmail.com

ACCOUNTABILITY MECHANISM OF WORLD BANK

The World Bank Inspection Panel is the independent complaint mechanism and fact-finding body for people who believe they are likely to be, or have been, adversely affected by a World Bank-financed project. If you submit a complaint to the Inspection Panel, they may investigate to assess whether the World Bank is following its own policies and procedures for preventing harm to people or the environment. You can contact the Inspection Panel or submit a complaint by emailing ipanel@worldbank.org. You can learn more about the Inspection Panel and how to file a complaint at: http://ewebapps.worldbank.org/apps/ip/Pages/Home.aspx.

Bank Documents

- Appraisal Project Information Document-Integrated Safeguards Data Sheet - Tuvalu Aviation Investment
- Tuvalu - Aviation Investment Project (TvAIP) : environmental assessment : Environmental and social m
- Tuvalu - Aviation Investment Project : third additional financing and restructuring (English)

Other Related Projects

- WB-P157779 Tuvalu Aviation Investment Project Additional Financing II