

 Early Warning System

IADB-DR-L1166

Climate Resilience Program for Bridge Infrastructure in the Dominican
Republic



Quick Facts

Countries	Dominican Republic
Financial Institutions	Inter-American Development Bank (IADB)
Status	Active
Bank Risk Rating	U
Voting Date	2024-07-17
Borrower	Government of Dominican Republic
Sectors	Climate and Environment, Transport
Investment Type(s)	Loan
Investment Amount (USD)	\$ 200.00 million
Project Cost (USD)	\$ 200.00 million



Project Description

The program's general objective is to contribute to the sustained and inclusive economic growth of the Dominican Republic. The specific objective is to improve the climate resilience of the country's bridge infrastructure.



Early Warning System Project Analysis

Likely to cause mostly local and short-term negative environmental and associated social impacts and for which effective mitigation measures are readily available



Investment Description

- Inter-American Development Bank (IADB)



Contact Information

ACCOUNTABILITY MECHANISM OF IADB

The Independent Consultation and Investigation Mechanism (MICI) is the independent complaint mechanism and fact-finding body for people who have been or are likely to be adversely affected by an Inter-American Development Bank (IDB) or Inter-American Investment Corporation (IIC)-funded project. If you submit a complaint to MICI, they may assist you in addressing the problems you raised through a dispute-resolution process with those implementing the project and/or through an investigation to assess whether the IDB or IIC is following its own policies for preventing or mitigating harm to people or the environment. You can submit a complaint by sending an email to MICI@iadb.org. You can learn more about the MICI and how to file a complaint at <http://www.iadb.org/en/mici/mici,1752.html> (in English) or <http://www.iadb.org/es/mici/mici,1752.html> (Spanish).



Bank Documents

- [Anexo EEO8 Puente-0007 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0011 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0058 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0064 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0069 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0088 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0094 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0102 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0106 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0121 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0184 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0187 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0190 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0191 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0302 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0303 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0305 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0314 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0747 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0830 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0861 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0917 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0918 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0929 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0951 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0952 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0953 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-0954 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1001 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1005 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1006 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1058 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1066 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1067 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1114 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1150 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1151 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1153 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1154 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1156 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1158 DR-L1166.docx](#) [Original Source]
- [Anexo EEO8 Puente-1172 DR-L1166.docx](#) [Original Source]