

 Early Warning System

IDBI-12858-01

BYD Salvador



## Quick Facts

<b>Countries</b>	Brazil
<b>Specific Location</b>	Salvador de Bahia
<b>Financial Institutions</b>	IDB Invest (IDBI)
<b>Status</b>	Proposed
<b>Bank Risk Rating</b>	A
<b>Voting Date</b>	2020-10-06
<b>Borrower</b>	Metrogreen Skyrail Concessionaria da Bahia S.A
<b>Sectors</b>	Construction, Infrastructure, Transport
<b>Investment Type(s)</b>	Loan
<b>Investment Amount (USD)</b>	\$ 240.00 million
<b>Loan Amount (USD)</b>	\$ 240.00 million



---

## Project Description

According to the Bank's website, this project finances the design, building and operation of a 23.28km, 26 station monorail line in Salvador de Bahia under the terms of a 35-year Public Private Partnership. Phase I runs from Ilha de Sao Joao station to Comercio station. Phase II goes from Porto São Joaquim station to Acesso Norte station.



---

## Investment Description

- IDB Invest (IDBI)



---

Private Actor 1	Private Actor 1 Role	Private Actor 1 Sector	Relation	Private Actor 2	Private Actor 2 Role	Private Actor 2 Sector
-	-	-	-	Metrogreen Skyrail Concessionária de Bahia SA	Client	-

---



---

## Contact Information

Client Contact name: Bianca Santos

Title: Project Manager

Phone number: +51 11 96320-9672

email address:

[bianca.santos@byd.com](mailto:bianca.santos@byd.com)

## ACCOUNTABILITY MECHANISM OF IADB

The Independent Consultation and Investigation Mechanism (MICI) is the independent complaint mechanism and fact-finding body for people who have been or are likely to be adversely affected by an Inter-American Development Bank (IDB) or Inter-American Investment Corporation (IIC)-funded project. If you submit a complaint to MICI, they may assist you in addressing the problems you raised through a dispute-resolution process with those implementing the project and/or through an investigation to assess whether the IDB or IIC is following its own policies for preventing or mitigating harm to people or the environment. You can submit a complaint by sending an email to [MICI@iadb.org](mailto:MICI@iadb.org). You can learn more about the MICI and how to file a complaint at <http://www.iadb.org/en/mici/mici,1752.html> (in English) or <http://www.iadb.org/es/mici/mici,1752.html> (Spanish).



## Bank Documents

- [ALVARD~1.PDF](#) [Original Source]
- [ANEXO 2-13-Estimativa-Demanda.pdf](#) [Original Source]
- [Anexo 2-4 -Canteiro de Obras\\_0.PDF](#) [Original Source]
- [Anexo-2-4-Patio-Premoldados\\_0.pdf](#) [Original Source]
- [ANEXO-ITEM-3 -MAPA\\_INFLUENCIA\\_MFBSocio.pdf](#) [Original Source]
- [ANEXO~1\\_0.PDF](#) [Original Source]
- [ANEXO~1\\_1.PDF](#) [Original Source]
- [ANEXO2~1\\_0.PDF](#) [Original Source]
- [CAPD ATUAL.pdf](#) [Original Source]
- [CI IBAMA.pdf](#) [Original Source]
- [CR Ibama 2020.pdf](#) [Original Source]
- [DE-M1.08.AE\\_P.FD2-001\\_0A.pdf](#) [Original Source]
- [DE-M1.08.AE\\_P.FD2-002\\_0A.pdf](#) [Original Source]
- [DE-M1.08.AE\\_P.FD2-003\\_0.pdf](#) [Original Source]
- [DE-M1.14.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.14.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-M1.16.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.16.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-M1.16.AE\\_P.FD2-003\\_0.pdf](#) [Original Source]
- [DE-M1.18.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.18.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-M1.18.AE\\_P.FD2-003\\_0.pdf](#) [Original Source]
- [DE-M1.18.AE\\_P.FD2-004\\_0.pdf](#) [Original Source]
- [DE-M1.20.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.22.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.22.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-M1.24.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.26.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.28.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.30.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.32.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.32.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-M1.34.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.34.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-M1.34.AE\\_P.FD2-003\\_0.pdf](#) [Original Source]
- [DE-M1.36.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.36.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-M1.38.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.40.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.42.AE\\_P.FD2-001\\_0.pdf](#) [Original Source]
- [DE-M1.42.AE\\_P.FD2-002\\_0.pdf](#) [Original Source]
- [DE-MG.00.SR\\_B.AM0-001\\_0\\_0.pdf](#) [Original Source]