Early Warning System

WB-P166099

Zambia-Tanzania Interconnector



Early Warning System

Zambia-Tanzania Interconnector

Quick Facts

Countries Tanzania, Zambia **Financial Institutions** World Bank (WB)

Bank Risk Rating

Borrower *Borrower information not provided at the time of disclosure*

Sectors Investment Type(s) Loan

Investment Amount (USD) \$ 210.00 million

Project Cost (USD) \$ 225.00 million

Project Description

Project description not provided at the time of disclosure*



Investment Description

• World Bank (WB)

Contact Information

Contact information not provided at the time of disclosure

ACCOUNTABILITY MECHANISM OF WORLD BANK

The World Bank Inspection Panel is the independent complaint mechanism and fact-finding body for people who believe they are likely to be, or have been, adversely affected by a World Bank-financed project. If you submit a complaint to the Inspection Panel, they may investigate to assess whether the World Bank is following its own policies and procedures for preventing harm to people or the environment. You can contact the Inspection Panel or submit a complaint by emailing ipanel@worldbank.org. You can learn more about the Inspection Panel and how to file a complaint at:

http://ewebapps.worldbank.org/apps/ip/Pages/Home.aspx.