

 Early Warning System

WB-P166099

Zambia-Tanzania Interconnector



## Quick Facts

<b>Countries</b>	Tanzania, Zambia
<b>Financial Institutions</b>	World Bank (WB)
<b>Bank Risk Rating</b>	A
<b>Borrower</b>	*Borrower information not provided at the time of disclosure*
<b>Sectors</b>	Energy
<b>Investment Type(s)</b>	Loan
<b>Investment Amount (USD)</b>	\$ 210.00 million
<b>Project Cost (USD)</b>	\$ 225.00 million



---

## Project Description

Project description not provided at the time of disclosure\*



---

## Investment Description

- World Bank (WB)



---

## Contact Information

*\*Contact information not provided at the time of disclosure\**

### **ACCOUNTABILITY MECHANISM OF WORLD BANK**

The World Bank Inspection Panel is the independent complaint mechanism and fact-finding body for people who believe they are likely to be, or have been, adversely affected by a World Bank-financed project. If you submit a complaint to the Inspection Panel, they may investigate to assess whether the World Bank is following its own policies and procedures for preventing harm to people or the environment. You can contact the Inspection Panel or submit a complaint by emailing [ipanel@worldbank.org](mailto:ipanel@worldbank.org). You can learn more about the Inspection Panel and how to file a complaint at: <http://ewebapps.worldbank.org/apps/ip/Pages/Home.aspx>.