Early Warning System

WB-P166796

Mali Electricity Sector Improvement Project (MESIP)



Early Warning System

Mali Electricity Sector Improvement Project (MESIP)

Quick Facts

Countries	Mali
Financial Institutions	World Bank (WB)
Status	Proposed
Bank Risk Rating	U
Borrower	Government of Mali
Sectors	Energy
Investment Amount (USD)	\$ 100.00 million
Project Cost (USD)	\$ 100.00 million



WB-P166796

Project Description

No project description provided at the time of disclosure



WB-P166796

Investment Description

• World Bank (WB)

WB-P166796

Contact Information

No project contacts provided at the time of disclosure

ACCOUNTABILITY MECHANISM OF WORLD BANK

The World Bank Inspection Panel is the independent complaint mechanism and fact-finding body for people who believe they are likely to be, or have been, adversely affected by a World Bank-financed project. If you submit a complaint to the Inspection Panel, they may investigate to assess whether the World Bank is following its own policies and procedures for preventing harm to people or the environment. You can contact the Inspection Panel or submit a complaint by emailing ipanel@worldbank.org. You can learn more about the Inspection Panel and how to file complaint http://ewebapps.worldbank.org/apps/ip/Pages/Home.aspx.



WB-P166796

Bank Documents

• Project Information