

 Early Warning System

WB-P167820

Energy Utility Performance and Reliability Improvement Project



---

## Quick Facts

<b>Countries</b>	Papua New Guinea
<b>Financial Institutions</b>	World Bank (WB)
<b>Status</b>	Proposed
<b>Bank Risk Rating</b>	B
<b>Borrower</b>	Government of Papua New Guinea
<b>Sectors</b>	Energy
<b>Investment Amount (USD)</b>	\$ 30.00 million
<b>Project Cost (USD)</b>	\$ 30.00 million



---

**Project Description**

No information available at the time of writing.



---

**Investment Description**

- World Bank (WB)



---

## Contact Information

\*No contact information available at the time of disclosure.

## ACCOUNTABILITY MECHANISM OF WORLD BANK

The World Bank Inspection Panel is the independent complaint mechanism and fact-finding body for people who believe they are likely to be, or have been, adversely affected by a World Bank-financed project. If you submit a complaint to the Inspection Panel, they may investigate to assess whether the World Bank is following its own policies and procedures for preventing harm to people or the environment. You can contact the Inspection Panel or submit a complaint by emailing [ipanel@worldbank.org](mailto:ipanel@worldbank.org). You can learn more about the Inspection Panel and how to file a complaint at: <http://ewebapps.worldbank.org/apps/ip/Pages/Home.aspx>.